

Erledigt

## i7 3770k Turbo funktioniert nicht

Beitrag von „Jenex79“ vom 5. Februar 2014, 00:43

Hi Leute,

habe das Problem, das meine CPU nur max bis 3.5 GHz hochgeht, obwohl sie im BIOS aus 3.9 Turbo eingestellt ist. SSDT Habe ich erstellt, EIST ist aus, Turbo manuell auf Multi 39 fixiert. SSDT Drop Haken...

Bin bei meiner Recherche auf

[Turbo maximal nur 3,5 Ghz - schon einiges versucht](#)

gestossen. Allerdings hat der User sein Wissen leider nicht weitergegeben 🙄

Bei ersten Ausführen des SSDT Schipptes bekomme ich folgende Fehlermeldung:

```
michaels-pro:~ Michael$ sudo /Users/Michael/Desktop/ssdtPRGen.sh 3900
```

```
sdtPRGen.sh v6.1 Copyright (c) 2013 by Pike R. Alpha
```

```
-----
```

```
Processor Declaration(s) Found in DSDT (ACPI 1.0 compliant)
```

```
Generating ssdt_pr.dsl for a MacPro5,1 [Mac-F221BEC8]
```

Ivy Bridge Core i7-3770K processor [0x0704] setup

With a maximum TDP of 77 Watt, as specified by Intel

Number logical CPU's: 8 (Core Frequency: 3500 MHz)

Number of Turbo States: 4 (3600-3900 MHz)

Number of P-States: 24 (1600-3900 MHz)

Injected C-States for CPU0 (C1,C3,C6)

Injected C-States for CPU1 (C1,C2,C3)

-e

**Warning: 'board-id' [Mac-F221BEC8] is not supported by Ivy Bridge PM**

Intel ACPI Component Architecture

ASL Optimizing Compiler version 20130117-64 [Jan 19 2013]

Copyright (c) 2000 - 2013 Intel Corporation

ASL Input: /Users/Michael/Desktop/ssdt\_pr.dsl - 260 lines, 8348 bytes, 56 keywords

AML Output: /Users/Michael/Desktop/ssdt\_pr.aml - 1599 bytes, 27 named objects, 29 executable opcodes

Compilation complete. 0 Errors, 0 Warnings, 0 Remarks, 0 Optimizations

-e

Do you want to copy /Users/Michael/Desktop/ssdt\_pr.aml to /Extra/ssdt.aml? (y/n)?y

michaels-pro:~ Michael\$