

Erledigt

Feintuning Siemens Workstation.

Beitrag von „MathiasOSX“ vom 1. September 2014, 10:49


Hallo zusammen,

ich freue mich hier zusein.

Ich habe ein Problem mit meinem Rechner/Laptop.

Es ist ein Siemens Workstation Rechner mit Mobile [Hardware](#).

Verbaut ist ein Intel T7400 und Intel GM945 Chipsatz (alles weitere siehe SystemInfo auf dem Bild):



The screenshot shows the 'System Info' window with the 'Devices' tab selected. It displays a list of hardware components with columns for Vendor ID, Vendor, Dev ID, Device, Class, and Subclass. The list includes various Intel components like PCI bridges, express ports, and controllers, as well as other hardware like C-Media Audio, Gigabit Ethernet, and USB controllers.

Vendor ID	Vendor	Dev ID	Device	Class	Subclass
8086	Intel Corporation	27b8	82801GB/GR (ICH7 Family) LPC Interface Bridge	Bridge	ISA bridge
8086	Intel Corporation	2444	82801 PCI Bridge	Bridge	PCI bridge
8086	Intel Corporation	27e2	82801GR/GH/GHM (ICH7 Family) PCI Express Port...	Bridge	PCI bridge
8086	Intel Corporation	27e0	82801GR/GH/GHM (ICH7 Family) PCI Express Port...	Bridge	PCI bridge
8086	Intel Corporation	2760	N10/ICH 7 Family PCI Express Port 1	Bridge	PCI bridge
8086	Intel Corporation	27a0	Mobile 945GM/GMS/GME, 943/940GML and 945G...	Bridge	Host bridge
8086	Intel Corporation	27a6	Mobile 945GM/GMS/GME, 943/940GML Express I...	Display contr...	Display contr...
8086	Intel Corporation	27a2	Mobile 945GM/GMS, 943/940GML Express Integr...	Display contr...	VGA compatib...
8086	Intel Corporation	2700	N10/ICH7 Family SATA IDE Controller	Mass storage...	IDE interface
1316	C-Media Electro...	0111	CM8738	Multimedia c...	Multimedia a...
8086	Intel Corporation	109a	82573L Gigabit Ethernet Controller	Network cont...	Ethernet cont...
8086	Intel Corporation	109a	82573L Gigabit Ethernet Controller	Network cont...	Ethernet cont...
8086	Intel Corporation	270a	N10/ICH 7 Family SMBus Controller	Serial bus co...	SMBus
10b9	Ali Corporation	5239	USB 2.0 Controller	Serial bus co...	USB Controller
10b9	Ali Corporation	5237	USB 1.1 Controller	Serial bus co...	USB Controller
10b9	Ali Corporation	5237	USB 1.1 Controller	Serial bus co...	USB Controller
10b9	Ali Corporation	5237	USB 1.1 Controller	Serial bus co...	USB Controller
8086	Intel Corporation	270c	N10/ICH 7 Family USB2 EHCI Controller	Serial bus co...	USB Controller
8086	Intel Corporation	270b	N10/ICH 7 Family USB UHCI Controller #4	Serial bus co...	USB Controller
8086	Intel Corporation	270a	N10/ICH 7 Family USB UHCI Controller #3	Serial bus co...	USB Controller
8086	Intel Corporation	2709	N10/ICH 7 Family USB UHCI Controller #2	Serial bus co...	USB Controller
10b9	Ali Corporation	5237	USB 1.1 Controller	Serial bus co...	USB Controller

Ich habe momentan 10.7.4 installiert.
und das Update auf 10.7.5 lade ich gerade herunter.

Folgende kette sind im momentan unter S/L/E installiert:

CMI8738AudioDevice.kext

ElliottForceLegacyRTC.kext

FakeSMC.kext

GenericUSBXHCI.kext

LegacyAppleRTC.kext

Patched_10.7_AppleRTC.kext

Einer der beiden AppleRTC Patschen geht nicht, muss noch mal schauen welcher.

Mein jetziges Problem ist, ich weiß nicht, wie ich die Grafik zum laufen bekomme?!


Sobald ich folgende Flags setze:

<key>Kernel Flags</key>

<string>arch=i386 -v</string>

bleibt mein System hängen.

Hier ein Bild von ChamäleonWizard:



Wie gehe ich nun am besten vor?

MFG Matze