

Erledigt

Nach Installation von MultiBeast lädt Hackintosh am Apple Logo ewig

Beitrag von „slicky“ vom 29. Oktober 2014, 18:36

Hier also da ist es stehen geblieben... Im abgesicherten Modus also habe es jetzt mit -v -x gemacht start er

```
Darwin Kernel Version 14.0.0: Fri Sep 19 00:26:44 PDT 2014; root:xnu-2782.1.97-2/RELEASE_ARM6_T801
va_page_bootstrap: 2020785 free pages and 68863 wired pages
kext submap [0xfffffffff8000000 - 0xfffffffff8000000], kernel text [0xfffffffff8000000 - 0xfffffffff8000000]
zone leak detection enabled
"va_compressor_node" is 4
waiting scheduler config: deep-drain 0, urgent first 1, depth limit 4, band limit 127, sanity check 8
standard timeslicing quantum is 10000 us
standard background quantum is 2500 us
sig_table_max_displ = 13
TSC Deadline Timer supported and enabled
MultiCPUPowerManagement::init: properties=0xfffffffff80104108
MultiCPUPowerManagement::start
FakeSMCKeyStore: started
AppleKeyStore starting (BUILT: Sep 19 2014 00:11:38)
AppleACPICPU: ProcessorId=1 LocalApicId=0 Enabled
AppleACPICPU: ProcessorId=2 LocalApicId=2 Enabled
AppleACPICPU: ProcessorId=3 LocalApicId=4 Enabled
AppleACPICPU: ProcessorId=4 LocalApicId=6 Enabled
calling smp_policy_init for TMSafetyNet
Security policy loaded: Safety net for Time Machine (TMSafetyNet)
calling smp_policy_init for RWF
Security policy loaded: Apple Mobile File Integrity (RWF)
calling smp_policy_init for Sandbox
Security policy loaded: Seatbelt sandbox policy (Sandbox)
calling smp_policy_init for Quarantine
Security policy loaded: Quarantine policy (Quarantine)
Copyright (c) 1982, 1989, 1993, 1991, 1993
The Regents of the University of California. All rights reserved.

MRC Framework successfully initialized
using 16384 buffer headers and 18248 cluster ID buffer headers
IDMPIC: Version 0x20 Vectors 64:07
ACPI: sleep states S3 S4 S5
pci (built 09:11:28 Sep 19 2014), flags 0xc3000, pfn64 (39 cpu) 0x7f0000000, 0x00000000
RCPIsensors (I280): 1 sensor added
RCPIsensors (I280): started
FakeSMC v6.11.1328 Copyright 2014 matias, slicc, usr-see2, kozlek, nevi, The KING, RehabMan. All rights reserved.
FakeSMC: 13 preconfigured keys added
SMC: successfully initialized
RCPIsensors (I281): 1 sensor added
RCPIsensors (I281): started
waitForSystemAppar
Backtrace 0xfffffffff8000005f54 0xfffffffff8000006a64 0xfffffffff80000072f6 0xfffffffff8000008e1d 0xfffffffff7f01fc8245 0xfffffffff800000b57ed 0xffff000000000000
Kernel Extensions in backtrace:
  com.apple.driver.AppleRTC(2.0)[003EF128-7287-3C01-B043-080E649907A7]0000000000000000->0xfffffffff7f01fc8245
  dependency: com.apple.iokit.IOPCIFamily(1.4)[70E2863E-A91A-3522-A1A0-75FD63E804C1]0000000000000000->0xfffffffff7f01fc8245
```