

**Erledigt**

## **Yosemite Installation auf Z97M-D3H**

**Beitrag von „tec-eng“ vom 7. April 2015, 23:22**

Dear Griven,

I installed Yosemite 10.10 again in the hackintosh and now I can not provide more description of the kernel panic. But at the moment of the update to Yosemite 10.10.2 , the hackintosh had only:

Z97MD3H -F5 - OZM - DSDT -G -1479 -M- SENSORS.rom,  
Yosemite 10.10 from AppStore and  
RealtekRTL8111.kext (installed by Kext Utility App).

Thank you very much for help me!