

Erledigt

Sicherheitsupdate 2015-004 -> Hacki bootet nur noch im Safe-Mode

Beitrag von „eny7785“ vom 17. November 2015, 20:20

im folgenden noch mein Fehlerbericht von OSX. Vielleicht hilft das ja?

Zitat

Anonymous UUID: EE3B83DD-4DC4-FE14-BEE0-F3C163311178

Tue Nov 17 19:58:52 2015

*** Panic Report ***

panic(cpu 0 caller 0xfffff8000416df2): Kernel trap at 0xfffff7f820b9e25, type 14=page fault, registers:

CR0: 0x000000008001003b, CR2: 0x0000000000000000, CR3: 0x00000003ff9c5037, CR4: 0x00000000001627e0

RAX: 0x00000006e3625cbe, RBX: 0x0000000000000000, RCX: 0x00000000471c6b88, RDX: 0x0000000000000004

RSP: 0xfffff81edb02fe0, RBP: 0xfffff81edb03010, RSI: 0xfffff80246dfe3c, RDI: 0xfffff8000a29d60

R8: 0xfffff7f8212ffc1, R9: 0x0000000000000008, R10: 0xfffff8000954b90, R11: 0x0000000000000000

R12: 0xfffff7f818aaa70, R13: 0xfffff7f818aaa70, R14: 0x0000000000000000, R15: 0xfffff80246dfc00

RFL: 0x0000000000010206, RIP: 0xfffff7f820b9e25, CS: 0x0000000000000008, SS: 0x0000000000000010

Fault CR2: 0x0000000000000000, Error code: 0x0000000000000000, Fault CPU: 0x0

Backtrace (CPU 0), Frame : Return Address

0xfffff81edb02c90 : 0xfffff800032ad21

0xfffff81edb02d10 : 0xfffff8000416df2

0xfffff81edb02ed0 : 0xfffff8000433ca3

0xfffff81edb02ef0 : 0xfffff7f820b9e25

0xfffff81edb03010 : 0xfffff7f820c0cba

0xfffff81edb03050 : 0xfffff80008d3dee

```
0xffffffff81edb03090 : 0xffffffff7f820c0378
0xffffffff81edb030e0 : 0xffffffff80008af4da
0xffffffff81edb03140 : 0xffffffff80008b9287
0xffffffff81edb03160 : 0xffffffff80008a9139
0xffffffff81edb031a0 : 0xffffffff80008af6d3
0xffffffff81edb031d0 : 0xffffffff80008af729
0xffffffff81edb03210 : 0xffffffff7f820b4bdd
0xffffffff81edb03240 : 0xffffffff80008af4da
0xffffffff81edb032a0 : 0xffffffff80008b9287
0xffffffff81edb032c0 : 0xffffffff80008a9139
0xffffffff81edb03300 : 0xffffffff80008af6d3
0xffffffff81edb03330 : 0xffffffff80008af729
0xffffffff81edb03370 : 0xffffffff80008af4da
0xffffffff81edb033d0 : 0xffffffff80008b9287
0xffffffff81edb033f0 : 0xffffffff80008a9139
0xffffffff81edb03430 : 0xffffffff80008af6d3
0xffffffff81edb03460 : 0xffffffff80008af729
0xffffffff81edb034a0 : 0xffffffff80008af4da
0xffffffff81edb03500 : 0xffffffff80008b9287
0xffffffff81edb03520 : 0xffffffff80008a9139
0xffffffff81edb03560 : 0xffffffff80008af6d3
0xffffffff81edb03590 : 0xffffffff80008af729
0xffffffff81edb035d0 : 0xffffffff80008af4da
0xffffffff81edb03630 : 0xffffffff80008b9287
0xffffffff81edb03650 : 0xffffffff80008a9139
0xffffffff81edb03690 : 0xffffffff80008af6d3
0xffffffff81edb036c0 : 0xffffffff80008af729
0xffffffff81edb03700 : 0xffffffff7f81e13df2
0xffffffff81edb03a50 : 0xffffffff7f813f2321
0xffffffff81edb03aa0 : 0xffffffff7f813f2234
0xffffffff81edb03ac0 : 0xffffffff7f813ee320
0xffffffff81edb03b10 : 0xffffffff7f813f86ff
0xffffffff81edb03b30 : 0xffffffff7f813f8e79
0xffffffff81edb03b60 : 0xffffffff80009014f4
0xffffffff81edb03bc0 : 0xffffffff80008fede3
0xffffffff81edb03d00 : 0xffffffff80003e1307
0xffffffff81edb03e10 : 0xffffffff800032ef8c
0xffffffff81edb03e40 : 0xffffffff80003139f3
0xffffffff81edb03e90 : 0xffffffff800032429d
0xffffffff81edb03f10 : 0xffffffff800040231a
0xffffffff81edb03fb0 : 0xffffffff80004344c6
Kernel Extensions in backtrace:
```

```
com.apple.driver.AppleHDA(272.18.3)[6893BD05-570A-3918-8477-
C60FC4AF5DE2]@0xffffffff7f820ab000->0xffffffff7f82155fff
dependency:  com.apple.driver.AppleHDAController(272.18.3)[BB6A5E87-4857-3FB8-
A979-505C84F52C9D]@0xffffffff7f81e0e000
dependency:  com.apple.iokit.IONDRVSupport(2.4.1)[7372D580-6DDE-3457-B043-
49B8447FC9D2]@0xffffffff7f8142b000
dependency:  com.apple.iokit.IOAudioFamily(203.3)[76E5591A-B495-3994-82C9-
D4AFE7248ACD]@0xffffffff7f8188c000
dependency:  com.apple.iokit.IOHDAFamily(272.18.3)[C5D86DE4-6E4E-310D-89B9-
DC0744020876]@0xffffffff7f81dff000
dependency:  com.apple.iokit.IOGraphicsFamily(2.4.1)[8922721D-5517-3883-BD3A-
57422D0244A0]@0xffffffff7f813e4000
dependency:  com.apple.driver.DspFuncLib(272.18.3)[324CB4BD-B0BA-32DF-BE23-
5879D2E2D93A]@0xffffffff7f81f7b000
```

BSD process name corresponding to current thread: WindowServer
Boot args: slide=0 kext-dev-mode=1

Mac OS version:
14F1021

Kernel version:
Darwin Kernel Version 14.5.0: Tue Sep 1 21:23:09 PDT 2015; root:xnu-
2782.50.1~1/RELEASE_X86_64
Kernel UUID: 06D286E3-A8A1-3BE7-A7EB-EAC6E0C69758
__HIB text base: 0xffffffff8000100000
System model name: MacPro3,1 (Mac-F42C88C8)

System uptime in nanoseconds: 19584745084
last loaded kext at 8229812313: com.apple.driver.AppleBluetoothMultitouch 85.3
(addr 0xffffffff7f81e5d000, size 73728)
loaded kexts:
at.obdev.nke.LittleSnitch 4352
org.hwsensors.driver.LPCSensors 1290
com.insanelymac.driver.AppleIntelE1000e 3.1.0
com.kext.HDAEnabler 1.0.0d1
org.hwsensors.driver.CPUSensors 1290
org.netkas.driver.FakeSMC 1290

com.apple.driver.AppleBluetoothMultitouch 85.3
com.apple.filesystems.autofs 3.0
com.apple.driver.AppleHDAHardwareConfigDriver 272.18.3
com.apple.driver.AppleHDA 272.18.3
com.apple.iokit.SCSITaskUserClient 3.7.5
com.apple.iokit.BroadcomBluetoothHostControllerUSBTransport 4.3.6f3
com.apple.driver.AppleGraphicsDevicePolicy 3.7.7
com.apple.driver.AppleUpstreamUserClient 3.6.1
com.apple.driver.AppleMCCSControl 1.2.12
com.apple.driver.AppleTyMCEDriver 1.0.2d2
com.apple.driver.AppleUSBCDC 4.3.3b1
com.apple.iokit.IOBluetoothSerialManager 4.3.6f3
com.apple.driver.AppleIntelHD5000Graphics 10.0.6
com.apple.driver.ACPI_SMC_PlatformPlugin 1.0.0
com.apple.driver.AppleFIVRDriver 4.1.0
com.apple.driver.AppleOSXWatchdog 1
com.apple.driver.AppleIntelFramebufferAzul 10.0.6
com.apple.driver.Apple16X50ACPI 3.2
com.apple.iokit.IOUserEthernet 1.0.1
com.apple.Dont_Steal_Mac_OS_X 7.0.0
com.apple.driver.AppleHWAAccess 1
com.apple.driver.AppleHV 1
com.apple.driver.AppleIntelSlowAdaptiveClocking 4.0.0
com.apple.driver.AppleFileSystemDriver 3.0.1
com.apple.AppleFSCompression.AppleFSCompressionTypeDataless 1.0.0d1
com.apple.AppleFSCompression.AppleFSCompressionTypeZlib 1.0.0
com.apple.BootCache 36
com.apple.driver.AppleUSBHub 705.4.2
com.apple.driver.XsanFilter 404
com.apple.iokit.IOAHCIBlockStorage 2.7.1
com.apple.iokit.IOAHCIPassThrough 1.0.3
com.apple.driver.AppleUSBXHCI 710.4.11
com.apple.driver.AppleUSBXHCI 705.4.14
com.apple.driver.AppleAHCIPort 3.1.2
com.apple.driver.AppleACPIButtons 3.1
com.apple.driver.AppleRTC 2.0
com.apple.driver.AppleHPET 1.8
com.apple.driver.AppleSMBIOS 2.1
com.apple.driver.AppleAPIC 1.7
com.apple.nke.applicationfirewall 161
com.apple.security.quarantine 3
com.apple.security.TMSafetyNet 8
com.apple.driver.IOBluetoothHIDDriver 4.3.6f3

com.apple.driver.AppleMultitouchDriver 264.6
com.apple.kext.triggers 1.0
com.apple.driver.DspFuncLib 272.18.3
com.apple.kext.OSvKernDSPLib 1.15
com.apple.iokit.IOBluetoothHostControllerUSBTransport 4.3.6f3
com.apple.driver.AppleGraphicsControl 3.10.25
com.apple.driver.AppleSMBusController 1.0.13d1
com.apple.iokit.IOSMBusFamily 1.1
com.apple.iokit.IOCSIBlockCommandsDevice 3.7.5
com.apple.iokit.IOUSBUserClient 705.4.0
com.apple.iokit.IOUSBHIDDriver 705.4.0
com.apple.iokit.IOUSBMassStorageClass 3.7.2
com.apple.iokit.IONDRVSupport 2.4.1
com.apple.driver.AppleHDAController 272.18.3
com.apple.iokit.IOHDAFamily 272.18.3
com.apple.iokit.IOAudioFamily 203.3
com.apple.vecLib.kext 1.2.0
com.apple.driver.IOPlatformPluginLegacy 1.0.0
com.apple.driver.IOPlatformPluginFamily 5.9.1d7
com.apple.driver.AppleUSBComposite 705.4.9
com.apple.driver.AppleSMBusPCI 1.0.12d1
com.apple.AppleGraphicsDeviceControl 3.10.25
com.apple.iokit.IOAcceleratorFamily2 156.16
com.apple.driver.Apple16X50Serial 3.2
com.apple.iokit.IOSerialFamily 11
com.apple.iokit.IOSurface 97.4
com.apple.iokit.IOGraphicsFamily 2.4.1
com.apple.iokit.IOBluetoothFamily 4.3.6f3
com.apple.iokit.IOSlowAdaptiveClockingFamily 1.0.0
com.apple.driver.AppleSMC 3.1.9
com.apple.iokit.IOCSIArchitectureModelFamily 3.7.5
com.apple.iokit.IOUSBFamily 720.4.4
com.apple.iokit.IOAHCIFamily 2.7.5
com.apple.iokit.IONetworkingFamily 3.2
com.apple.driver.AppleEFINVRAM 2.0
com.apple.driver.AppleEFIRuntime 2.0
com.apple.iokit.IOHIDFamily 2.0.0
com.apple.security.sandbox 300.0
com.apple.kext.AppleMatch 1.0.0d1
com.apple.driver.AppleKeyStore 2
com.apple.driver.AppleMobileFileIntegrity 1.0.5
com.apple.driver.AppleCredentialManager 1.0
com.apple.driver.DiskImages 398

com.apple.iokit.IOStorageFamily 2.0
com.apple.iokit.IOReportFamily 31
com.apple.driver.AppleFDEKeyStore 28.30
com.apple.driver.AppleACPIPlatform 3.1
com.apple.iokit.IOPCIFamily 2.9
com.apple.iokit.IOACPIFamily 1.4
com.apple.kec.corecrypto 1.0
com.apple.kec.Libm 1
com.apple.kec.pthread 1
Model: MacPro3,1, BootROM MP31.006C.B05, 2 processors, Intel Core i3, 3.6 GHz, 16 GB, SMC 1.30f3
Graphics: Intel HD Graphics 4600, Intel HD Graphics 4600, Built-In
Memory Module: BANK 0/DIMM1, 8 GB, DDR3, 1600 MHz, Kingston, KHX1600C10D38G
Memory Module: BANK 0/DIMM3, 8 GB, DDR3, 1600 MHz, Kingston, KHX1600C10D38G
Bluetooth: Version 4.3.6f3 16238, 3 services, 27 devices, 0 incoming serial ports
Network Service: Ethernet, Ethernet, en0
Serial ATA Device: Samsung SSD 850 EVO 250GB, 250,06 GB
USB Device: Hub
USB Device: Hub
USB Device: BCM20702A0
USB Device: USB Flash Drive
USB Device: USB KEYBOARD
Thunderbolt Bus:

Alles anzeigen