

Erledigt

{Diskussion} Z97X-UD3H, i7 4790k, GTX 970, SoundBlaster SB1040, BCM94360CD, El Capitan USB FIX

Beitrag von „uiop“ vom 6. April 2016, 19:38

[Zitat von steff89](#)

Hey [@uiop](#)

I don't have the problem you describe.

Have you used the ozmosis bios and DSDT provided with the guide, or have you created your own? If you have created your own, maybe something went wrong there. You should be able to use the BIOS and DSDT files provided with the guide. Only the SSDT you can not use, because you have another CPU.

Greetings,
Steffen

I created my own bios because I wanted to integrate everything (FakePCIID_XHCIMux.kext, FakePCIID.kext, AppleIntelE1000e.kext) into bios and didn't want to rename EHC1/EHC2 to EH01/EH02. (like [@al6042](#)) I'm also using a patch for AppleHDA by toleda to use integrated alc1150 audio...

I'll try and use yours (next time I have the time) just to diagnose the problem and report back



Thank you