

Erledigt

# E6400 Nvidia NVS 160M (not Intel GMA) EL Capitan CLOVER


Beitrag von „Capitan-Paule“ vom 13. April 2016, 21:36

So Halbzeit. Leider hat das nicht geklappt. Anbei paar Bilder

```
SuperIODevice: [Fatal] found unsupported chip! IIE sequence ID=0x4680, Winbond sequence ID=0xffff
AMFI_LoadTrustedKeysFromNVRam: no nvram variable
using 16384 buffer headers and 10240 cluster IO buffer headers
ncache: 2 CPU(s), 64 bytes CPU cache line size
mbinit: done [64 MB total pool size, (42/21) split]
rooting via boot-uuid from /chosen: 2C6A668D-BE8A-3767-BE85-DD23D8921DD7
com.apple.AppleFSCompressionTypeDataless kmod start
com.apple.AppleFSCompressionTypeZlib kmod start
No interval found for . Using 80000000
com.apple.AppleFSCompressionTypeDataless load succeeded
com.apple.AppleFSCompressionTypeZlib load succeeded
AppleIntelCPUPowerManagementDriver: ready
IO80211Controller::createIOReporters 0xd2d882d414aaf6b3
CCFlags: 0x0, CCLLevel: 5 ConsoleFlags: 0x0, ConsoleLevel: -1
No Service found 10000024e
configureInterests - nElements <= 0!Failed to addSubscription for group Chip subgroup Bytes Transferred driver
3 - data underrun
IO80211ControllerMonitor::configureSubscriptions() failed to add subscriptionIO80211Controller::start_control
4aaf6b3, provider is 0xd2d882d3b5bf87b3
FireWire (DHCI) VendorID 1180 ID 832 PCI now active, GUID 364fc80021863090; max speed s400.
Waiting on <dict ID="0"><key>IOProviderClass</key><string ID="1">IOResources</string><key>IOResourceMatch</key>
ot-uuid-media</string></dict>
ath_get_caps[4044] rx chainmask mismatch actual 3 sc_chainmak 0
3.398515: ath_get_caps[4019] tx chainmask mismatch actual 3 sc_chainmak 0
3.410453: Atheros: mac 128.2 phy 13.0 radio 12.8
3.415712: Use hw queue 0 for WME_AC_BE traffic
3.420941: Use hw queue 1 for WME_AC_BK traffic
3.426132: Use hw queue 2 for WME_AC_VI traffic
3.431240: Use hw queue 3 for WME_AC_VO traffic
3.436271: Use hw queue 8 for CAB traffic
3.441178: Use hw queue 9 for beacons
AirPort_AtherosNewma40::apple80211RequestIoctl type 0xc cmd GET
AirPort_AtherosNewma40::apple80211RequestIoctl type 0xe cmd GET
3.456372: ATHR: getPHY_MODE unexpected ioctl call when vap is deleted
init: error getting PHY_MODE; using MODE_UNKNDOWN
AirPort_AtherosNewma40::apple80211RequestIoctl type 0x50 cmd GET
3.472190: wlan_vap_create : enter. devhandle=0x756ac8e0, opmode=IEEE80211_M_STA, flags=0x1
3.478151: wlan_vap_create : exit. devhandle=0x756ac8e0, opmode=IEEE80211_M_STA, flags=0x1.
bpfAttach len 88 dlt 127
bpfAttach len 124 dlt 192
bpfAttach len 24 dlt 105
3.497611: ATH tunables:
3.501887: pullmode[1] txringsize[ 256] txsendqsize[1024] reapmin[ 32] reapcount[ 128]
GeForceSensors: still waiting for accelerator to start...
GeForceSensors: still waiting for accelerator to start...
**** [IOBluetoothFamily][SearchForTransportEventTimeoutHandler] -- Missing Bluetooth Controller Transport!
GeForceSensors: still waiting for accelerator to start...
```







Ist es Vllt einfacher, aus dem Mavericks System zu installieren?

Heißt ich starte meine alte Festplatte mit Mavericks und pack in des HDD-Caddy die neue Festplatte wo EL Capitan drauf soll. Starte dann den installer aus Mavericks raus...

Gesendet von iPhone mit Tapatalk