

Erledigt

El Capitan AMD FX Installation hilfe

Beitrag von „SkylineMusic“ vom 15. Mai 2016, 13:54

Okay ich habe mal von dem DPCIManager 2 Screenshots gemacht, wenn das das richtige ist



edit: Ich habe jetzt vorübergehend die "maus" über die "Remote Mouse" app aus dem App Store über mein Handy laufen.

DPCIManager

Extract DSDT
Repair Perms
Rebuild Cache
Install Kext
P States
Update Seed
Update IDs
Submit List

Status
PCI List
Misc

Vendor	Device	Sub Ven	Sub Dev	Vendor Name	Device Name
1002	5A14	1002	5A14	Advanced Micr...	RD890 PCI to PCI bridge (exter...
1002	5A16	0000	0000	Advanced Micr...	RD890 PCI to PCI bridge (PCI ex...
1002	5A19	0000	0000	Advanced Micr...	RD890 PCI to PCI bridge (PCI ex...
1002	5A1D	0000	0000	Advanced Micr...	RD890 PCI to PCI bridge (exter...
1002	4391	1462	7741	Advanced Micr...	SB7x0/SB8x0/SB9x0 SATA Con...
1002	4397	1462	7741	Advanced Micr...	SB7x0/SB8x0/SB9x0 USB OHCI...
1002	4396	1462	7741	Advanced Micr...	SB7x0/SB8x0/SB9x0 USB EHCI...
1002	4397	1462	7741	Advanced Micr...	SB7x0/SB8x0/SB9x0 USB OHCI...
1002	4396	1462	7741	Advanced Micr...	SB7x0/SB8x0/SB9x0 USB EHCI...
1002	4385	1462	7741	Advanced Micr...	SBx00 SMBus Controller
1002	4383	1462	7741	Advanced Micr...	SBx00 Azalia (Intel HDA)
1002	439D	1462	7741	Advanced Micr...	SB7x0/SB8x0/SB9x0 LPC host c...
1002	4384	0000	0000	Advanced Micr...	SBx00 PCI to PCI Bridge
1002	4399	1462	7741	Advanced Micr...	SB7x0/SB8x0/SB9x0 USB OHCI...
1002	4397	1462	7741	Advanced Micr...	SB7x0/SB8x0/SB9x0 USB OHCI...
1002	4396	1462	7741	Advanced Micr...	SB7x0/SB8x0/SB9x0 USB EHCI...
1022	1600	0000	0000	Advanced Micr...	Family 15h Processor Function 0
1022	1601	0000	0000	Advanced Micr...	Family 15h Processor Function 1
1022	1602	0000	0000	Advanced Micr...	Family 15h Processor Function 2
1022	1603	0000	0000	Advanced Micr...	Family 15h Processor Function 3
1022	1604	0000	0000	Advanced Micr...	Family 15h Processor Function 4
1022	1605	0000	0000	Advanced Micr...	Family 15h Processor Function 5
10EC	8168	1462	7741	Realtek Semic...	RTL8111/8168/8411 PCI Expre...
1002	AA98	1682	AA98	Advanced Micr...	Caicos HDMI Audio [Radeon HD...
1821	1042	1462	7741	ASMedia Tech...	ASM1042 SuperSpeed USB Host...
1002	6779	1682	3207	Advanced Micr...	Caicos [Radeon HD 6450/7450...

Bridge, Host bridge

DPCIManager

Extract DSDT
Repair Perms
Rebuild Cache
Install Kext
P States
Update Seed
Update IDs
Submit List

Status
PCI List
Misc

Model	BSD	Builtin
RTL8168E-VL/8111E-VL	en0	<input checked="" type="checkbox"/>

Model	Framebuffer	Ports
AMD Radeon HD 6xxx	ATY,AMD,RadeonFram...	3

Audio Device	Sub Device	Codec ID	Revision	Codec Name*
0x10024383	0x14627741			
0x1002AA98	0x1682AA98			

Model	Type	Location	Phy Block
SanDisk SDSSDP128G	SATA	Internal	512
Hitachi HTS543216L9SA00	SATA	Internal	512

*Courtesy of the VoodooHDA project