

Erledigt

OZMOSIS REQUEST THREAD / Ozmosis Anfragen [1. Beitrag beachten!]

Beitrag von „robertnclayton“ vom 24. Juni 2016, 05:33

AFUDOS with / GAN can not flash .CAP files. Error:. ROM filesize does not match existing BIOS size

. .CAP Contains additional 2Kb header

Who handled this problem? My ASUS motherboard does not have dual-bios or other recovering tools - I have only one attempt: D

Sorry, I only speak english. I have the same board and have attempted to flash the same CAP file with the same result "rom file size does not match existing BIOS size" Off by about 2kb. If It helps I generated MMTTool reports for each file and diff'd them ... but I do not know how to fix?

pastebin.com/RKQYyLfy