

# {Anleitung} Acer Aspire E15 - ES-571-358U i3 5005 - Intel HD 5500

Beitrag von „Bombeiros“ vom 23. Oktober 2016, 15:54

```
FileObjKey = 0xFFFF0000
paniclog 2 caller: 0xFFFFFFFFeaf3f8: assertArg/Library/Caches/com.apple.xnu/Sources/GPU/Driver/Intel/G
Debugger called: Open()
Backtrace (CPU 2), From: Return Address
0xFFFFFFFF3278c00 : 0xFFFFFFFF31f74c
0xFFFFFFFF3278c00 : 0xFFFFFFFFeaf3f8
0xFFFFFFFF3278c00 : 0xFFFFFFFFeaf3f8
0xFFFFFFFF3278c00 : 0xFFFFFFFFeaf3f8
0xFFFFFFFF3278c00 : 0xFFFFFFFFeaf3f8
0xFFFFFFFF3278c00 : 0xFFFFFFFFeaf3f8
0xFFFFFFFF3278c00 : 0xFFFFFFFFeaf3f8
0xFFFFFFFF3278c00 : 0xFFFFFFFFeaf3f8
Kernel Extensions in backtrace:
com.apple.driver.AppleIntelSGMUPhysicalFrameBuffer [0, 0] (20160805-5013-3092-00FC-201000F14F280F1F)
dependency: com.apple.lak11.iOPCIFamily2.5.1 (2.5.1) (20160805-5013-3092-00FC-201000F14F280F1F)
dependency: com.apple.lak11.iOPCIFamily1.4.1 (4.1) (20160805-2496-3F71-022C-027000F231800F1F1F1F1F1F1F)
dependency: com.apple.lak11.iOPCIFamily1.2.0 (1.2) (20160805-2496-3F71-022C-027000F231800F1F1F1F1F1F1F)
SuperIODevice: 0x0000000000000000
dependency: com.apple.lak11.iOPCIFamily1.2.0 (1.2) (20160805-2496-3F71-022C-027000F231800F1F1F1F1F1F1F)
dependency: com.apple.lak11.iOPCIFamily1.2.0 (1.2) (20160805-2496-3F71-022C-027000F231800F1F1F1F1F1F1F)
OS process name corresponding to current thread: kernel_task
root args: -r /private//com.apple.Recovery.Json/RecoverySystem.dmg
Mac OS version:
16D029
Kernel version:
Darwin Kernel Version 16.0.0: Tue Aug 23 22:03:12 PDT 2016; root:xnu-2001.1/2~3/RELEASE_ARM_T804
Kernel UUID: 82004794-240-3249-0000-000000000000
Kernel slide: 000000001f000000
__ELF__ header: 0xFFFFFFFF1f000000
System model name: MacBookA15,1 (Mac-443EC2090000000)
System uptime in microseconds: 1499124019
```

Hier nun diese Fehlermeldung von diesen Laptop Modell: ES1-571-307T