Gigabyte Z97X-UD3H VS ASRock Z97 EXTREME

Beitrag von "372Dragon" vom 12. Dezember 2016, 14:18

Hi everybody, especially Asrock-man's!

As z97 extreme6 owner, have some question:

Flashed oszm 2.70 bios (Crusher), installed (clean) 10.12.1 from scratch. Everything seems working - even both NICs, only trouble is at the moment sleep/shut down - in both cases computer goes restart. Is there something missing? Can not figure out... bios settings? DSDT? This is bit new an different here in Asrock world.