

Apple Airport Karten BCM943602CS & BCM94360CD mit PCI-E Adapter günstig in Asien bestellen

Beitrag von „derpuma“ vom 3. Januar 2017, 22:01

Hatte ich doch gepostet! Unter Bluetooth steht nichts zur Verfügung.



Bei dir wird ja unter USB auch ein Bluetooth USB Host Controller erkannt, bei mir steht lediglich BCM2045A0...

Laut Rehabman Seite sollten die Kexte die du mir geschickt hast in S/L/E nicht in L/E?
Sollte ich das mal versuchen?

Zitat

More Installation Details
BrcmPatchRAM.kext and BrcmPatchRAM2.kext can be installed either through Clover kext injection or placed in /System/Library/Extensions. Install only one, not both, depending on system version.

BrcmFirmwareRepo.kext does not work with Clover kext injection, unless using a device specific firmware injector. BrcmFirmwareData.kext can work with Clover kext injection.

You can also use a device specific firmware injector (in conjunction with BrcmFirmwareRepo.kext). In this scenario, BrcmFirmwareRepo.kext does work from Clover kexts.

You will find device specific injectors in the 'firmwares' directory of the git repository. They are not included in the distribution ZIP.

Alles anzeigen

Update: Die Kexte in S/L/E brachten auch keine Besserung!