

Erledigt

gtx 660 clover hdmi sound

Beitrag von „al6042“ vom 19. März 2017, 16:32

What do you mean with "start intel 4000"?

Did you just change the order in your BIOS?

You might need some changes to your AppleIntelFramebufferCapri.kext.

Since you use Ozmosis, which cannot handle on-the-fly injects to Kexts, you have to use the following terminal commands

Code

1. sudo perl -pi -e 's|\x02\x05\x00\x00\x00\x04\x00\x00\x07\x04\x00\x00|\x02\x05\x00\x00\x08\x00\x00\x06\x00\x00|' /System/Library/Extensions/AppleIntelFramebufferCapri.kext/Contents/MacOS/AppleIntelFramebufferCapri.kext
2. sudo perl -pi -e 's|\x03\x04\x00\x00\x00\x04\x00\x00\x81\x00\x00\x00|\x03\x04\x00\x00\x08\x00\x00\x06\x00\x00|' /System/Library/Extensions/AppleIntelFramebufferCapri.kext/Contents/MacOS/AppleIntelFramebufferCapri.kext
3. sudo perl -pi -e 's|\x04\x06\x00\x00\x00\x04\x00\x00\x81\x00\x00\x00|\x04\x06\x00\x00\x08\x00\x00\x06\x00\x00|' /System/Library/Extensions/AppleIntelFramebufferCapri.kext/Contents/MacOS/AppleIntelFramebufferCapri.kext
4. sudo touch /System/Library/Extensions/