

Erledigt

## Update für macOS Sierra 10.12.4

Beitrag von „den4ik“ vom 31. März 2017, 23:56

[Ralf](#)

Habs gefunden und eingestellt, dennoch sieht mein Boot Vorgang so aus

```
incomplete channel sequence length 0, should be 16
en1: channel changed to 1
en1: channel sequence length 0, should be 16
IO80211Interface::postMessage bssid changed
bpfAttach len 94 dlt 163
bpfAttach len 30 dlt 105
bpfAttach len 52 dlt 127
bpfAttach len 38 dlt 192
IO80211Interface::updateReport _peerManager is missing
AirPort_Brcm4360::getSSIDData(): Get failure: APPLE80211_IOC_SSID: 6
prevent idle sleep list: IODisplayWrangler+ (1)
AirPort_Brcm4360_P2PInterface::init name <p2p0> role 1
IO80211VirtualInterface::init _controller is 0x892deb6a28921f47, prov
configureInterests - nElements <= 0!Failed to configure interests
IO80211Controller::addSubscriptionForThisReporterFetchedOnTimer() Fai
p Interface p2p0 subgroup Data Packets driver 0x892deb6a28921f47 - da
IO80211InterfaceMonitor::configureSubscriptions() failed to add subsc
AirPort_Brcm4360_P2PInterface::init <p2p> role 1
AirPort_Brcm4360_P2PInterface::init name <awdl0> role 4
AirPort_Brcm4360_P2PInterface::awdlAttachToBpf name <awdl0> role 4 su
IO80211VirtualInterface::init _controller is 0x892deb6a28921f47, prov
Creating all peerManager reporters
AirPort_Brcm4360_P2PInterface::init <awdl> role 4
ARPT: 6.712823: AirPort_Brcm43xx::syncPowerState: WWEN[disabled]
awdl0: promiscuous mode enable succeeded
awdl0: promiscuous mode disable succeeded
awdl0: promiscuous mode enable succeeded
busy timeout[0], (60s), kextd wait(0): 'AppleACPICPU'
busy timeout[1], (60s), kextd wait(0): 'AppleACPICPU'
IOConsoleUsers: time(0) 0->0, lin 0, llk 1,
IOConsoleUsers: gIOScreenLockState 3, hs 0, bs 0, now 0, sm 0x0
```

Danach passiert einfach nix . Der Rechner bleibt stundenlang so

Update :

Der Rechner bootet jetzt , allerdings läuft die Nvidia Grafik Karte nicht mehr. Neue WebDriver

hat das OS bekommen , aktiviert wurde es durch einen Eintrag unter SystemParameters .. wobei Nvda\_drv wurde auch probiert. Der Rechner bootet ausschließlich mit nv\_disable=1.

Das Update hat mich echt viel Zeit geraubt .

Wäre sehr dankbar wenn jemand weis ,wie mann so einen WebDriver wieder imGang kriegt und nv-disable wieder los .