

Erledigt

Ozmosis problem with ASUS MAXIMUS VII HERO

Beitrag von „al6042“ vom 11. Juni 2017, 13:23

That's the correct one..

I've attached a new Defaults.plist for your System, which you should put to /EFI/Oz and then do an NVRAM-Reset.

The NVRAM-Reset is done by using and holding the following keys while the System is either in the BIOS or the Boot-Selection:

Alt+WinLogo+P+R

The System should reboot and startup with the Ozmosis-Logo... Good Luck