

Erledigt Intel DG45ID DSDT Anfrage

Beitrag von „cobanramo“ vom 22. Juli 2017, 20:46

Ich glaub bin ein bisschen weitergekommen, wenn ich unter Uefi/Bios HPET aktiviere kommt sofort KP wie oben im anderen post, wenn ich den HPET deaktiviere und im config.plist HPET Fix wähle geht es recht weiter kurz vor dem start der oberfläche kommt dann eben dieses neue KP mit der meldung **"No HPETs available... CPU(s) configured incorrectly"**. Hat keiner einen tip für mich?

```
Jul 22 08:35:29 2017 localhost com.apple.smc.Launchd[1] (com.apple.AmbiLightService[131]) (Warning): Endp
...
Jul 22 08:36:05 2017 localhost com.apple.smc.Launchd[1] (com.apple.system.notification) (Info): Please
...
Jul 22 08:36:11 2017 localhost com.apple.smc.Launchd[1] (Error): assertion failed: 15631: Launchd + 20
...
Jul 22 08:36:25 2017 localhost com.apple.smc.Launchd[1] (com.apple.system.log) (Info): This key da
...
Jul 22 08:36:25 2017 localhost com.apple.smc.Launchd[1] (com.apple.trustd.agent) (Error): The ServiceM
...
Jul 22 08:36:26 2017 localhost com.apple.smc.Launchd[1] (com.apple.trustd.agent) (Info): This
...
Jul 22 08:36:26 2017 localhost com.apple.smc.Launchd[1] (com.apple.smc.Launchd) (Error): E
...
Jul 22 08:36:26 2017 localhost com.apple.smc.Launchd[1] (com.apple.smc.Launchd) (Error): E
...
Debugger called: Queue()
kern_return_t Queue() {
    return 0;
}
Kernel Extensions in BootStage0:
com.apple.driver.AppleIntelCPUPowerManagement (218-813688708-9135-3951-520C-170181938182)
...
Darwin Kernel Version 15.4.0: Thu Aug 23 18:25:34 PDT 2016; root:xnu-4903.202~1/RELEASE_ARM_T8040
...
Debugger not configured. Hanging.
```