

Erledigt

Gelöst: El Capitan, Lenovo s430: HDMI/DP-Out, HDMI Audio und internes Mic.

Beitrag von „griven“ vom 30. November 2017, 22:31

There are a bunch of ACPI patches needed alongside to Rehabmans ACPIBatteryManager.kext to make the battery meter work properly. In the attached file (based on the DSDT published in post #12) I added the needed patches to make it work. Please give it a try and let me know wether it worked for you or not 😊