

Erledigt Hp 8470p Fixes!

Beitrag von „christoforosgr“ vom 6. April 2018, 14:37

Yes, that worked really well, and it is persistent across reboots!

I was suspecting that there was something wrong with colour depth, as every monitor (internal and iMac) was reported to use a 30-Bit (ARG210210210) Framebuffer depth under System Report-> Hardware -> Graphics/Displays instead of 24-Bit (ARG888888).

Really simple workaround, as it does not require a reboot to apply, perhaps a fine-tune in EDID (if possible) will make it more "elegant", but that's something for later 😊