

Erledigt

Mac OS Sierra auf Dell Optiplex 760 installieren

Beitrag von „Ntvfrank“ vom 8. April 2018, 17:42

Moin moin,

ich wollte heute mal versuchen mir High Sierra auf den folgenden Rechner zu bringen:

- Optiplex 780 mit Q9550 Core 2 Quad CPU
- 8 GB Speicher
- GT 710 Grafikkarte
- 500 GB Platte.

Install Clover in the ESP
Bootloader / Install boot0af in the MBR
CloverEFI / Clover-EFI 64Bit SATA
Drivers64UEFI / EmuVariableUefi-64
Drivers64UEFI / OsxAptioFixDrv-64
Drivers64UEFI / PartitionDxe-64

Ich habe die Datei von KayKun mir runtergeladen. Dann habe ich das ausgepackte CLOVER.ZIP File in die EFI Partition kopiert und den vorhandenen CLOVER Ordner überschrieben..

Rechner startet und ich komme dann in das Utility Programm und kann die Festplatte formatieren. Wenn ich dann OSX installiere bekomme ich diese Fehlermeldung und es geht nicht weiter. Ich habe das Protokoll gespeichert, weiss aber nicht wie ich das hochladen kann, hier die letzten paar Zeilen:

```
IASSetCurrentInstallPhase: Current phase name set to "Language Chooser"  
Apr 8 15:21:37 iMac Language Chooser[528]: AppleSecureBootFailureReason: 0x00,  
StartupManagerFailureReason: 0x00  
Apr 8 15:21:37 iMac Language Chooser[528]: Not hiding Language Chooser in window counter  
Apr 8 15:21:37 iMac Language Chooser[528]: ISAP: Done with Phase "Language Chooser"  
Apr 8 15:21:37 iMac Installer Progress[177]: IASSetCurrentInstallPhase: Current phase name  
set to "Language Chooser"
```

Apr 8 15:21:37 iMac Installer Progress[177]: Done with phase = "Language Chooser"
Apr 8 15:21:37 iMac Installer Progress[177]: IASSetCurrentInstallPhase: Current phase name set to "Language Chooser"
Apr 8 15:21:37 iMac Installer Progress[177]: IASClearInstallProgress: Clearing Registry
Apr 8 15:21:37 iMac Installer Progress[177]: Ending progress UI via 100% progress
Apr 8 15:21:37 iMac Installer Progress[177]: Setting window alpha values to 0.0
Apr 8 15:21:37 iMac Installer Progress[177]: Ordering windows out
Apr 8 15:21:42 iMac Unknown[529]: Keyboard Layouts: duplicate keyboard layout identifier -14934.
Apr 8 15:21:42 iMac Unknown[529]: Keyboard Layouts: keyboard layout identifier -14934 has been replaced with -28673.
Apr 8 15:30:23 iMac powerd[170]: Display is turned off
Apr 8 15:30:23 iMac powerd[170]: Assertion Summary. Type:ExternalMedia Name:'com.apple.powermanagement.externalmediamounted' Id:0x800008000 Process:powerd [System: No Assertions]
Apr 8 15:31:10 iMac powerd[170]: Assertion Created. Type:UserIsActive Name:'com.apple.iohideventsystem.queue.tickle.4294968408.17' Id:0x90000800a Process:hidd [System: DeclUser kDisp]
Apr 8 15:31:10 iMac powerd[170]: Display is turned on
Apr 8 15:31:19 iMac InstallAssistant_springboard[559]: Springboarding to: /Volumes/Image Volume/Install macOS High Sierra.app/Contents/MacOS/InstallAssistant
Apr 8 15:31:19 iMac InstallAssistant_springboard[559]: argv[0]: InstallAssistant
Apr 8 15:31:19 iMac InstallAssistant_springboard[559]: argv[1]: - NSDisabledCharacterPaletteMenuItem
Apr 8 15:31:19 iMac InstallAssistant_springboard[559]: argv[2]: YES
Apr 8 15:31:19 iMac InstallAssistant_springboard[559]: argv[3]: -AppleKeyboardUIMode
Apr 8 15:31:19 iMac InstallAssistant_springboard[559]: argv[4]: 2
Apr 8 15:31:19 iMac InstallAssistant_springboard[559]: argv[5]: -AppleLanguages
Apr 8 15:31:19 iMac InstallAssistant_springboard[559]: argv[6]: (de)
Apr 8 15:31:19 iMac InstallAssistant_springboard[559]: argv[7]: -RunInOSIEnv
Apr 8 15:31:20 iMac Unknown[529]: objc[559]: Class OSISSystemInfo is implemented in both /Volumes/Image Volume/Install macOS High Sierra.app/Contents/MacOS/InstallAssistant (0x10651eec8) and /Volumes/Image Volume/Install macOS High Sierra.app/Contents/Frameworks/OSInstallerSetup.framework/Versions/A/OSInstallerSetup (0x114d36a70). One of the two will be used. Which one is undefined.

Habt ihr einen Tip für mich?

Viele Grüße aus Rheinhessen

Frank

iMac i5 von 2010 mit High Sierra