

Erledigt

ASRock Z370 Extreme4 fast perfekt...aber...

Beitrag von „cyberdott“ vom 1. Mai 2018, 00:42

hier die Ausgabe:

Index Refs Address Size Wired Name (Version) UUID <Linked Against>

```
17 4 0xffffffff7f81f67000 0x1f000 0x1f000 as.vit9696.Lilu (1.2.3) 9C714621-4E3B-37F7-9439-49FB5355317B <7 5 4 3 2 1>
```

```
18 0 0xffffffff7f81f86000 0x56000 0x56000 as.lvs1974.IntelGraphicsFixup (1.2.7) C2ADBDC5-5DD-3CF4-A8AF-A6146F0F5D4B <17 12 7 5 4 3 2 1>
```

```
21 0 0xffffffff7f8380a000 0xc000 0xc000 as.lvs1974.NvidiaGraphicsFixup (1.2.6) DE5F7EC7-0837-322C-9A53-BFACB5ACF10B <17 7 5 4 3 2 1>
```

```
39 0 0xffffffff7f840d8000 0x4000 0x4000 com.rehabman.driver.USBInjectAll (0.6.5) A63DACD5-10FE-3A1C-BCB1-4EEF5308B7CC <12 11 4 3>
```

```
40 0 0xffffffff7f840dd000 0x7000 0x7000 as.vit9696.Shiki (2.2.6) F280FCE5-E6DC-3DE1-AEBE-6DE56E2D4798 <17 7 5 4 3 2 1>
```

```
41 3 0xffffffff7f840e4000 0x11000 0x11000 org.netkas.driver.FakeSMC (1787) 48B68964-E812-3912-B518-AB8750DC2D22 <11 7 5 4 3 1>
```

```
44 0 0xffffffff7f840f5000 0x8000 0x8000 org.tw.CodecCommander (2.6.3) 6032938E-4161-35BC-9507-DE73BFA6ABB3 <43 12 11 4 3 1>
```

```
45 0 0xffffffff7f84104000 0xd8000 0xd8000 as.vit9696.AppleALC (1.2.6) 7CCD3E13-609E-39E3-A3AB-6596F38B38AE <17 12 7 5 4 3 2 1>
```

46 0 0xffffffff7f841dc000 0x5000 0x5000 org.hwsensors.driver.CPUSensors (1787) ED90DA0F-5876-3DB5-82EC-CEEA470A7479 <41 7 5 4 3>

69 0 0xffffffff7f841e2000 0xd000 0xd000 org.hwsensors.driver.LPCSensors (1787) EF5BB9DC-C33F-3EED-9F96-42A7F22D806F <41 12 11 7 5 4 3>

70 0 0xffffffff7f841ef000 0x25000 0x25000 com.insanelymac.IntelMausiEthernet (2.3.0) 59520ABC-940A-3B82-83EE-6BB7F6299230 <15 12 5 4 3 1>

71 0 0xffffffff7f84225000 0x12000 0x12000 org.hwsensors.driver.GPUSensors (1787) C6BE6BDA-2398-3318-BCF0-F519AD4DB140 <41 12 11 7 5 4 3>

121 0 0xffffffff7f81346000 0x4000 0x4000 com.intel.driver.EnergyDriver (2.0) 7FE9AF4A-A8C2-3099-A956-971DDC86A467 <7 5 4 3>

128 2 0xffffffff7f80b90000 0x679000 0x679000 com.nvidia.web.NVDAResmanWeb (10.3.1) 8E2AB3E3-4EE5-3F90-B6D8-54CEB8595A5F <114 95 93 12 7 5 4 3 1>

129 0 0xffffffff7f813ed000 0x1a7000 0x1a7000 com.nvidia.web.NVDAGP100HalWeb (10.3.1) 0CDFBF48-5CD7-3C97-A083-A7E179C25654 <128 12 4 3>

131 0 0xffffffff7f81751000 0xa8000 0xa8000 com.nvidia.web.GeForceWeb (10.3.1) B4761F6B-66C5-3512-BD13-2CCC7BCC1868 <128 114 94 93 12 7 5 4 3 1>

154 0 0xffffffff7f81855000 0x2000 0x2000 com.nvidia.CUDA (1.1.0) 4329B052-6C8A-3900-8E83-744487AEDEF1 <4 1>

USB über USBInjectall

WLAN über nen PCIE-Adapter:

Kartentyp: AirPort Extreme (0x14E4, 0x133)

Firmware-Version: Broadcom BCM43xx 1.0 (7.77.37.29.1a7)

Quicksync ist für mich mit der App Reflector 3 gelöst.