

**In Arbeit**

## **Xiaomi Air 12,5" | M3-7Y30 | 4GB RAM | HD 615 | SSD 128GB**

**Beitrag von „influenist“ vom 14. Mai 2018, 14:31**

Hi, I found an adapter that should fix internal wifi support using a M.2 Key M adapter board which has 943602CS. For BT you need USB lanes, so I ordered one without USB soldering cables (means no BT) and one with USB soldering cables. I'll update you as soon as I receive the boards. Earlier I tested a board M.2 Key M to Key A+B with module yet that didn't work. This one is original designed for the Mi Notebook PRO so it should be working with the 12.5 also.