

Erledigt

Does Oz understand Xeon CPU's and how to make it work?

Beitrag von „firefly_can_fly“ vom 3. Juni 2018, 00:39

Yes, I've reset NVRAM couple times, even reflashed bios, couple times for original —> Oz rom, restoring [bios settings](#) and still all the same.

What I did today is:

All that I did yesterday, tried to flash OZ, but eventually, nothing is happening.

The methodology was like this:

- 1) Flash Oz infused ROM, hit ESC, bios setting to default and then make them proper. Reset
- 2) Hit f12 for boot menu and performing NVRamm rest (screen is flickering, reboot)
- 3) After boot, OZ "infusion" part and loading SSD with Mac Os installed - nothing. Not verbose mode or HDD activity on a computer case.
- 4) Logging again into bios, turning off CSM - same result.
- 5) Installing MacOs 10.13 USB drive and fresh unused SSD - same thing, just black screen, and nothing moving forward.

All these steps I performed with 3 Oz [distros](#), and still, the result is the same. Windows working without any problems, what's wrong with Oz and why it's not loading - I don't even understand. TO eliminate the problem with "corrupted from" all these countless bios reflashes were performed by 3 different flash drives and checksum of ROM files were the same. SO bios files are not corrupted.

I don't understand the direction where to dig in, because of nothing unusual been made, and if there were something magical, other things are not affected by it.

p.s. P-RAM Reset - for some reason i call it NVRAM reset.