

**Erledigt**

## **[English] I need some help with Mojave and Z77X-UD5H and Ozmosis. This is the best place, but I don't speak German. Can anyone help?**

**Beitrag von „griven“ vom 19. Juni 2018, 23:10**

Well no need to take german lessons at all 😊

My best guess is that some SMBIOS settings and maybe also the APFS driver used in the Rom are outdated.

Critical values are BiosVersion, BiosReleaseDate, FirmWare Features and FeaturesMask. Apple shipped Firmware Updates for most mac models with all major versions of HighSierra to ensure highest possible compatibility with APFS. The HighSierra Installer checks whether the Firmware is up to date or not and if not it tries to initiate a Firmware Update which of course will fail on non Apple Hardware. To keep a long Story short try this one: [Z77XUD5H.16j.zip](#)

What I did:

- > Update SMBIOS Information
- > Replace APFS Driver

Let me know if it works for you 😊