

Erledigt

AirDrop funktioniert, Handoff jedoch nicht

Beitrag von „nr_123“ vom 28. Juli 2018, 10:18

Hi Leute,

Versuche aktuell meinem Hack den letzten schliff zu verpassen, es funktioniert alles iMessage, Facetime, AirDrop usw usw jedoch will das verfluchte Handoff nicht funktionieren.

Handoff ist im System aktiviert. Ich besitze eine Wlan-BT Karte aus einem MacBook Air 2012, laut Spezifikationen kann diese Karte das besagte alles.

Ich verwende jedoch die Karte nur für Wlan da ich die BT Funktion nicht zum laufen bekommen habe, trotz der separaten USB Zuleitung. Für BT verwende ich einen Stick der auch Plug and Play funktioniert hat ohne Treiber, der Hersteller ist Cambridge Silicon Radio und es ist ein BT 4.0 Stick welcher mit der Maus oder Tastatur auch ohne Probleme funktioniert.

Ich hab mal das Tool Continuity-Activation laufen lassen und bekomme folgende Diagnose:

--- Hardware/OS checks ---

Verifying Continuity status... OK. OS X reports Continuity as active

Verifying Mac model reference... OK. Known compatible Mac Model detected: iMac13,2

Verifying Mac board-id... OK. Long board id detected: Mac-FC02E91DDD3FA6A4

Verifying OS X version... Warning: This tool wasn't tested with OS X versions higher than 10.10. Detected OS version: 10.13.6

Verifying Wi-Fi hardware... WARNING. An unknown/untested AirPort card using the 'BrcmNIC' kext is active. This tool can't fix this.

Verifying AWDL status... OK. An AWDL interface is up, Wi-Fi is ready for Continuity

Verifying Bluetooth hardware... WARNING. No Bluetooth controller references were found in the PRAM, dongles can't be detected.

Verifying Bluetooth version... OK. Bluetooth 4.0 detected

Verifying Bluetooth features... WARNING. Unknown Bluetooth features have been detected (code:6). This tool can try to fix this.

Verifying Bluetooth firmware... OK. Bluetooth firmware version: v187 c8891

Verifying Login Item... OK. Login item for Auto Continuity Check is not set.

--- Modifications check ---

Verifying OS kext protection... OK. Kext developer mode is not active. This tool can fix this.

Verifying kexts readability... OK. Wi-Fi and Bluetooth kexts were found and could be read

Verifying Wi-Fi whitelist status... OK. The whitelist is incorrectly patched, your board-id wasn't found at the right place. This tool can try to fix this.

Verifying BT4 dongles compatibility... OK. Compatibility with BT4 USB dongles is not enabled, this tool can fix this if a dongle is plugged in

Verifying old Wi-Fi kext presence... OK. Legacy Brcm4331 Wi-Fi driver is present. This tool can fix this.

Verifying legacy Wi-Fi card patch... OK. The legacy Wi-Fi patch is not present. This tool can fix this.

--- Modifications check ---

Ich weis damit nicht wirklich viel anzufangen, deswegen wäre ich um Hilfe dankbar 😊