

Erledigt

## Audio layout-id not inject. Ozmosis [EN]

Beitrag von „MrVanosh“ vom 31. August 2018, 18:37

1 or 3. I see in your DSDT version it's 2 but in ioreg is still 7.

[@kuckkuck](#) I see also HDAS section in SSDT-4 maybe changing it to HDEF will help. nvm previously I renamed B0D3 to HDAS (facepalm) I will edit with result

Changing layout-id in DSDT change alc-layout-id in ioreg

next edit: ehh I don't have ideas. For ALC1150 I can also inject 7 and with this injection same issue.