

Erledigt **Hp 8470p Fixes!**

Beitrag von „ssprod“ vom 29. September 2018, 02:58

I switched the 3 wire leads on to pins 2+3 and it worked! I have a **strange issue**, however... I own 2 x 8470P's with the same specs and the AMD GPU. One is working flawlessly with this EFI, however on the other machine, when I boot Safari, I get this screen. I made sure that I changed to 8bit in ResExtreme. Any help would be most appreciated, thanks very much.