

Anleitung: High Sierra auf HP Elitebook 8460p mit Intel Core i7-2620M und ATI HD 6470M

Beitrag von „gamal“ vom 6. November 2018, 22:22

Thanks brother anonymous writer

Thanks God

Definition of AMD Radeon HD 6470M Series 1024 MB

correctly

On the latest version of High Sierra 10.13.6

Most jobs work except

Control the screen lighting even though the lighting switches are working but not affected

Of course, the Wi-Fi Card is not defined

The sleep mode does not work

I have tried a lot to know AMD Radeon HD 6470 m

On a system of scavengers but to no avail

Any one has the idea to help solve the remaining problems I have him from the complainant



