

Erledigt

Neues Projekt: Hack Mini mit NUC nuc7i7dnke,16 GB RAM und NVME SSD

Beitrag von „eltanque“ vom 31. Dezember 2018, 17:42

in Clover wird sie angezeigt, im biosbootmenü auch, aber das starten bricht irgendwann ab. ich hänge mal ein Foto an, hoffentlich ist genug zu erkennen.

```

1000002.429406 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
:swcrypto_threadpool_init:1325: 4 threads would be used for the ThreadPool
:swcrypto_threadpool_worker_thread:1249: ThreadPool worker thread started
:swcrypto_threadpool_worker_thread:1249: ThreadPool worker thread started
:swcrypto_threadpool_worker_thread:1249: ThreadPool worker thread started
:dev_init:285: disk0s2: device accelerated crypto: 0 (compiled @ Nov 12 2018 21:50:35)
:swcrypto_threadpool_worker_thread:1249: ThreadPool worker thread started
:dev_init:288: disk0s2: device_handle block size 4096 block count 12285436 features 0 internal
:fletcher64_init:106: Selecting AVX2 implementation of fletcher64
:flletcher64_init:106: disk0s2: initializing cache w/hash_size 8192 and cache size 32768
:mx_kernel_mount:1206: disk0s2: checkpoint search: largest xid 9123, best xid 9123 @ 88
:mx_kernel_mount:1455: disk0s2: done registering sysctls.
:apfs_sysctl_register:926: done registering sysctls.
Ethernet (IntelMausi): 1219V4 (Rev. 33), 94:c6:91:a4:56:e0
1000002.804422 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.821567 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.838711 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.855887 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.873065 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.890189 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.907019 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.923828 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.940584 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.940584 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000003.237627 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
:BrmPatchRAM2: Version 2.2.10 starting on OS X Darwin 18.2, using possible compatible personality.
:BrmPatchRAM2: Unknown new Darwin version 18.2, using possible compatible personality.
:BrmPatchRAM2: Published new IOKit personality for BrmPatchRAMResidency.
:BrmPatchRAM2: Published new IOKit personality for BrmPatchRAMResidency.
HID: Legacy shim 2
:BrmPatchRAM2: Published new IOKit personality for BrmPatchRAMResidency.
:BrmPatchRAM2: Published new IOKit personality for BrmPatchRAMResidency.
HID: Legacy shim 2
RTC: Only single RAM bank (128 bytes)
HID: Legacy shim 2
pci (build 20:32:40 Nov 12 2018), flags 0x20e3000
VirtualSMC: efend 0 failed to find valid status (0000000000000000, 0), VirtualSMC EFI module is broken
VirtualSMC: efend 0 no extra rtc memory is present for key erase
[ PCI configuration begin ]
[ PCI configuration end, bridges 5, devices 15 ]
AppleNVRAM: Assertion failed: FIDMapRegs ErrorExit file: /BuildRoot/Library/Caches/com.apple.xbs/Sources/IONVRAMFamily/IONVRAMFamily-307.230.1/IONVRAMController.cpp line: 979
AppleNVRAM: Assertion failed: result DeleteWorkLoop file: /BuildRoot/Library/Caches/com.apple.xbs/Sources/IONVRAMFamily/IONVRAMFamily-307.230.1/IONVRAMController.cpp line: 979
Copyright (c) 1982, 1986, 1989, 1991, 1993
The Regents of the University of California. All rights reserved.
MRC Framework successfully initialized
using 16384 buffer headers and 10240 cluster IO buffer headers
wcache: 4 CPU(s), 64 bytes CPU cache line size
mbinit: done 195 MB total pool size, (64/32) split
com.apple.AppleFSCompressionTypeZlib load start
com.apple.AppleFSCompressionTypeDataless load start
1000002.373464 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.383816 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
:calling mpo_policy_init for ASP
:Security policy loaded: Apple System Policy (ASP)
com.apple.AppleFSCompressionTypeZlib load succeeded
com.apple.AppleFSCompressionTypeDataless load succeeded
Ethernet (IntelMausi): TCP/IPv4 segmentation offload disabled.
rooting via boot-uuid from /chosen: 34211521-4E03-3C10-8463-C62827D696F9
Waiting on <dict ID="0"><key>IOProviderClass</key><string ID="1">IOResources</string></key></dict>
Ethernet (IntelMausi): TCP/IPv6 segmentation offload disabled.
Ethernet (IntelMausi): TCP/IPv6 checksum offload enabled.
Ethernet (IntelMausi): Version 2.4.0 using max interrupt rate 7000. Please don't support tonyacx86.com!
:crypto_ioctl:1682: Using 64 buffers with size 16384, 512 buffers size 65536
1000002.416825 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
:swcrypto_threadpool_init:1303: Starting ThreadPool
1000002.429406 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
:swcrypto_threadpool_init:1325: 4 threads would be used for the ThreadPool
:swcrypto_threadpool_worker_thread:1249: ThreadPool worker thread started
:swcrypto_threadpool_worker_thread:1249: ThreadPool worker thread started
:swcrypto_threadpool_worker_thread:1249: ThreadPool worker thread started
:dev_init:285: disk0s2: device accelerated crypto: 0 (compiled @ Nov 12 2018 21:50:35)
:swcrypto_threadpool_worker_thread:1249: ThreadPool worker thread started
:dev_init:288: disk0s2: device_handle block size 4096 block count 12285436 features 0 internal
:fletcher64_init:106: Selecting AVX2 implementation of fletcher64
:flletcher64_init:106: disk0s2: initializing cache w/hash_size 8192 and cache size 32768
:mx_kernel_mount:1206: disk0s2: checkpoint search: largest xid 9123, best xid 9123 @ 88
:mx_kernel_mount:1455: disk0s2: done registering sysctls.
:apfs_sysctl_register:926: done registering sysctls.
Ethernet (IntelMausi): 1219V4 (Rev. 33), 94:c6:91:a4:56:e0
1000002.804422 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.821567 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.838711 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.855887 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.873065 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.890189 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.907019 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.923828 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.940584 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000002.940584 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
1000003.237627 AppleUSBHostResources@: AppleUSBHostResources:allocateDownstreamBusCurrentGated: assuming successful wakelimits 150 sleepUnits 0
:BrmPatchRAM2: Version 2.2.10 starting on OS X Darwin 18.2, using possible compatible personality.
:BrmPatchRAM2: Unknown new Darwin version 18.2, using possible compatible personality.
:BrmPatchRAM2: Published new IOKit personality for BrmPatchRAMResidency.
:BrmPatchRAM2: Published new IOKit personality for BrmPatchRAMResidency.
HID: Legacy shim 2
:BrmPatchRAM2: Published new IOKit personality for BrmPatchRAMResidency.
:BrmPatchRAM2: Published new IOKit personality for BrmPatchRAMResidency.
HID: Legacy shim 2

```