

Erledigt

Mit FBPatcher die richtige PlatformID für UHD620 gefunden - klappt trotzdem nicht


Beitrag von „TNa681“ vom 17. Januar 2019, 18:59

The Acer Bios doesn't allow to setup custom video memory, means the memory is forced by the IGPlatform via the FBPatcher tool.

I am not using a SSDT. Once I am back home (later today) I'll upload my entire EFI Folder so you can investigate it deeply.

Edit:

[anonymous writer](#) Das Erstellen der .TXT via Terminal hat leider nicht funktioniert (siehe beigefügtes Bild)



```
ubuntu@ubuntu:~$ sudo apt-get install get-edid
Reading package lists... Done
Building dependency tree
Reading state information... Done
E: Unable to locate package get-edid
ubuntu@ubuntu:~$ get-edid > ~/Desktop/DUMP-EDID.txt
Command 'get-edid' not found, but can be installed with:
sudo apt install read-edid
ubuntu@ubuntu:~$ get-edid > ~/Desktop/DUMP-EDID.txt
Command 'get-edid' not found, but can be installed with:
sudo apt install read-edid
ubuntu@ubuntu:~$ sudo apt-get install get-edid
Reading package lists... Done
Building dependency tree
Reading state information... Done
E: Unable to locate package get-edid
ubuntu@ubuntu:~$
```