

**Erledigt**

# Mojave 10.14.4 Probleme mit EmuVariableUefi-64.efi und ASUS Prime Z-390-A

Beitrag von „l3rry“ vom 1. April 2019, 07:53



Index Refs Address Size Wired Name (Version) UUID <Linked Against>

37 5 0xfffff7f8588b000 0x11000 0x11000 org.netkas.driver.FakeSMC (1800) FC7031CC-C949-35D1-AC1A-CA8DB349793E <12 8 6 5 3 1>

38 2 0xfffff7f8589c000 0x22000 0x22000 as.vit9696.Lilu (1.3.5) 426CBF1D-1638-3D7A-9EB1-17525E0C1A6E <8 6 5 3 2 1>

39 0 0xfffff7f858be000 0x63000 0x63000 as.vit9696.WhateverGreen (1.2.7) 1544DA5A-9156-34FE-9B5E-050B5F758B6B <38 13 8 6 5 3 2 1>

40 0 0xfffff7f85921000 0x107000 0x107000 as.vit9696.AppleALC (1.3.6) 7414811A-6394-3B45-9283-47D61F255E19 <38 13 8 6 5 3 2 1>

41 0 0xfffff7f85a28000 0x6000 0x6000 org.hwsensors.driver.CPUSensors (1800) ED90DA0F-5876-3DB5-82EC-CEEA470A7479 <37 8 6 5 3>

49 0 0xfffff7f85a2e000 0x4000 0x4000 org.hwsensors.driver.SMMSensors (1800) 97DDF4ED-310B-3123-988E-E1A9890743A6 <37 8 6 5 3>

56 0 0xfffff7f85a32000 0xa000 0xa000 org.hwsensors.driver.ACPIsensors (1800) FA4DF6C0-0D3A-3CE2-8569-0AB2C84053E7 <37 12 8 6 5 3>

64 0 0xfffff7f85a3c000 0x21000 0x21000 com.insanelymac.IntelMausiEthernet (2.4.1d1)

88E228F4-3264-385C-84E9-3B7F99112336 <16 13 6 5 3 1>

65 0 0xffffffff7f85a5d000 0xd000 0xd000 org.hwsensors.driver.LPCSensors (1800) EF5BB9DC-C33F-3EED-9F96-42A7F22D806F <37 13 12 8 6 5 3>

66 0 0xffffffff7f85a6a000 0x15000 0x15000 org.hwsensors.driver.GPUSensors (1800) C6BE6BDA-2398-3318-BCF0-F519AD4DB140 <37 13 12 8 6 5 3>

Hab virtualSMC durch FakeSMC wieder getauscht. Also nicht verwirren lassen...

Ich glaube das beste ist ich setz den Hacki mal neu auf...