

# USBInjectAll - Immer aktuell (wenn's geht)

Beitrag von „arigata9“ vom 17. Mai 2019, 20:38

Hier mal wieder ein Update mit folgenden Änderungen:

2018-11-08 (0.7.1)

- add MacBookAir8,1 and Macmini8,1
- remove EHCI configuration (EH01/EH02/HUB1/HUB2) from models which are unlikely to need it
- remove matching for AppleBusPowerControllerUSB, which was used in old versions of macOS (note: AppleBusPowerController should still match)
- change SSPx to SS0x in 8086\_8xxx
- reduce Info.plist size
- rename all SSPx -> SS0x for consistency
- remove kernel flag -uia\_exclude\_ssp