

acidanthera VirtualSMC (Wird zum Boot benötigt)

Beitrag von „Noir0SX“ vom 3. Juli 2019, 15:43

v1.0.5

- Allow loading on 10.15 without `-lilubetaall`
- Fixed SMCBatteryManager compatibility with 10.15
- Changed RGEN 3 -> 2 for AppleIntelPCHPMC.kext compatibility

v1.0.4

- Removed exposed REV, RBr, RPlt keys from I/O Registry
- Minor EFI driver compatibility improvements
- Synced RVUF, RVFB with REV from booter keys
- Fixed prebuilt revisions for GEN 3 chip emulation
- Dropped custom prebuilt revisions in favour of loader inject