

Acer Swift 5 Mojave 10.14.5 Update Problem...

Beitrag von „larson“ vom 21. Dezember 2019, 11:07

i test first EFI, i've got black screen just after few second.

I try fakeid on intel, but no luck.

I'm on bios 1.2 with this config, seems ok ?

i try second efi, blackscreen after 10 seconds too

I update my bios to 1.4 and extract original ACPI .. files join, no best result for now.

Here is my last test, with SSDT-XOSI.aml, SSDT-HWP.aml, DSDT.aml in patched folder. I remove ssdt.aml who make blackscreen at launch

Any idea ?