Umsetzung prüfen Ozmosis mit macOS Catalina 10.15 - OZ167X-XMAX (extended)

Beitrag von "nokiachangzhi" vom 19. März 2020, 15:46

you have a customised USBPorts.kext?
OK,Thanks very much. ROM is attached.
1. In * - V * mode, I wait for about 1-2 minutes, and the screen will be black. The system cannot be started and can not enter the desktop. You can see the pointer by shaking the mouse, but when you click the mouse, the pointer disappears. You can only force a reboot.
2. Because I customized more than 15 USB ports, I need to remove the system's limit on the total number of USB ports. Later, I removed all the settings and driver files about USB, but the above problems still exist.

<u>nokiachangzhi</u> Please attach your ROM. Have you waited a little longer in Verbose to see if any more messages pop up? And why do you use a PortLimit Kext-Patch when

So, where is the problem? Is my machine not compatible with Ozmosis? However, as long as you enter the system, everything is OK. I'm really dizzy...

3. In fact, I finally reduced the number of files inserted into BIOS, and removed the unimportant drivers and redundant parameters (if there is no darboot, the machine can't find the nvme SSD, so darboot can't be removed); I also replaced the SMC, but it can't solve the above problems. The ROM(2020-3-10 V5.rom) I submitted in the attachment is the last simplified version I tested (I added shell for debugging convenience). The problem still exists.

and

The following ROM 2020-3-9 last.rom is not reduced. The SMC version is also different from the simplified version.

But the problem remains.

Zitat von kuckkuck

Danke.