

Erledigt

## Natives Thunderbolt3 an jedem Rechner

Beitrag von „foojitsu1“ vom 25. April 2020, 15:38

[Zitat von IndioX](#)

I don't understand, why don't you dare say that it is a cMP?

in addition, initializing the card via win warmboot would not be illegal - UAD simply does not want to

and when I read the messages of some users, luna does not work with the original firmware either.

edit: it is due to the lack of AVX support

[https://en.m.wikipedia.org/wiki/Advanced\\_Vector\\_Extensions](https://en.m.wikipedia.org/wiki/Advanced_Vector_Extensions)

Alles anzeigen

[IndioX](#) Agree. Other users on UAD Forum are saying AVX (or lack of) is the issue with MacPro5,1.

@Nustic Even with TR card removed, exact same error occurs. It's not related to card or custom firmware.

Not sure if this is worth mentioning, but Intel has AVX Emulator for MacOS. Unfortunately, I haven't figured out (yet) how to load properly for validation purposes ...

<https://software.intel.com/en-...ware-development-emulator>

My background is limited. Maybe someone with more experience can comment?