

MSR Unlock/Cascade Lake Refresh Firmware Fix

Beitrag von „Extreme“ vom 18. Juli 2020, 20:00

Hi,

In bios 2002 the sleep works perfectly. Today I updated to 3101 and, with the same [bios settings](#) of 2002, the stop no longer works on Catalina.