

macOS 11 BigSur Dev-Beta Clover Patch

Beitrag von „ITzTravellnTime“ vom 7. August 2020, 16:02

I get this kernel panic when trying booting on my x99 system (featuruing an i7 5820k, a gigabyte x99 soc champion and an r9 280x)

I upgraded my catalina efi folder according to what i read here and i have seen that i got kext injection to work properly but i can't boot because of this.

