

# HP EliteBook 840 G1 & OpenCore Catalina/Big Sur

Beitrag von „gingerbread“ vom 6. September 2020, 21:36

Thank you for your help. I have tried the myvar test; it works after a reboot. But at a second reboot; the Reset NVRAM or Clean NVRAM doesnt do anything; as the myvar is still in NVRAM.