

# OpenCore and MSI Rx 5500XT

Beitrag von „asheenlevrai“ vom 15. September 2020, 14:30

## [Zitat von Aluveitie](#)

Then I don't know. I dismantled my rig recently to upgrade so I cannot check what value my old RX 5500 XT had...

It does not work without the ATY,Rom property injected? The bug is described within the installer, so it should run without any injected properties/ACPI renames as far as I understand the issue.

Thanks 😊

I removed ATY,Rom# and indeed nothing changed.

Not better, not worse

In the beginning, I also thought that I shouldn't add anything in DeviceProperties (only the boot-arg and the kernel->patch, as described in the installer guide on Dortania). However this didn't work either. Maybe now I should revert and see how different it was compared to where I am now...

## [Zitat von apfelnico](#)

"WhateverGreen.kext" should provide any correct values. Only the specification of the "PCI slot" `_COULD_` look a bit strange due to the ACPI (not optimized for macOS).

If you want to change that, the entry "AAPL, slot-name" is sufficient. For this I would use the value "Slot-1" instead of "Internal ...", because the graphics card is in a PCIe slot and is not integrated on the mainboard.

Thanks 😊

Should I replace "internal@0,3,1/0,0" with "slot-1" or rather "slot-1@(something)"?