

I9900K Z390 MSI Gaming Pro Carbon Clover Install

Beitrag von „Designexe“ vom 29. September 2020, 22:22

Moin Leute,

ich versuche gerade mit einem Kumpel sein Hackintosh zum laufen zu bekommen, leider mit mäßigem erfolg.

Die Installation bricht direkt ab.

Der PC ist gerade frisch zusammengebaut, also kein Windows installiert.

```
B|`CS:CSKSD] {
B|`CS:CSKSD] Err(0xE) @ GV 8D63D4FE-BD3C-4AAD-881D-86FD974
B|`G:CS] } Ok(0)
B|`WL:PWL FNV] Err(0x5) @ GV wake-failure
B|`WL:DT] Err(0x5) @ WL:PWL FNV
B|`LD:LKC] BPDK -> (System\Library\PrelinkedKernels\prelink
B|`LD:OFS] Err(0xE) @ OPEN (System\Library\PrelinkedKerne
B|`LD:LKC] BPDK,!R -> (System\Library\PrelinkedKernels\prel
B|`LD:LKFS] } Ok(0)
B|`LD:LKC] } Ok(0)
B|#FWFM] 0xFF1FFF7F
B|#FWFT] 0xE80FE136
B|#CSR:OUT] 0X000003E7
B|`BST:FBS] {
B|`BST:FBS] BA.ADSZ: 0
B|`BST:FBS] BA.KSDSZ: 0
B|`B:WFDW] Err(0xE), 0 @ LochB 71B4903C-14EC-42C4-8DC6-CE1449
B|#LOG:DT] 2020-09-30T04:27:12
B|#STOP|`BST:FBS] ! @ MM:AKM 297791488 @ 'RT
B|#WL|6] 0x01 0x03 23 0x0E
biting efiboot...
B|#WL|7] 0x01 0x03 23 0x0E
ot failed; will sleep for 10 seconds before exiting...
B|#LOG:EXIT] 2020-09-30T04:27:12
ror: Aborted returned from boot.efi

as error, press any key

hit any key to continue *_
```

[CLOVER.zip](#)