

Lenovo Thinkpad T530

Beitrag von „5T33Z0“ vom 19. Oktober 2020, 19:21

[antukst](#) Don't put your answer in my quote as if I said it, please!

Check in BIOS for:

Sata Mode: XHCI

Bootmode: UEFI Only

CSM: Disabled

Fingerprint Scanner: disabled

WAN: disabled

EXACT CPU MODEL? (as in i7 **3xxx**)

Try disabling all Kexts containing "Brcm..." in Config > Kernel > Add