

Lenovo Thinkpad T530

Beitrag von „5T33Z0“ vom 19. Oktober 2020, 19:43

[antukst](#) Please disable Entry "CPU Power Management" in ACPI > Add > 2 as well. It's for a different CPU. Might not fix the issue, though.