

Lenovo Thinkpad T530

Beitrag von „5T33Z0“ vom 23. Oktober 2020, 23:31

[antukst](#) I just learned that MacBookPro10,1 SMBIOS doesn't work for BigSur. You need to use MacBookPro15,1 instead.