

X299 Tutorial - ASUS WS X299 SAGE/10G (Hilfe und Diskussionen)

Beitrag von „mokapuccino“ vom 11. November 2020, 10:55

Hi everyone

I have some problems with my hackintosh.

First, when I turn off the hack completely and want to turn it on again, it runs in a vacuum with a black screen.

not even an Asus bios, nothing.

to turn it on again I have to force it to turn off by keeping the power button pressed.

then at the second ignition it boots normally but the bios starts in safe mode.

Why ?? 😞

second, my thunderbolt card is well recognized by IORegistry except that it does not appear in "system report" "thunderbolt : No driver loaded."

and of course when I turn off the hack and want to turn it on again (it needs to be turned on twice for it to run properly) the thunderbolt card is no longer recognized.

Probably because of bios safe mode

thank you for your possible lights

