

In Arbeit

Dell Latitude 7370 | 10.15.5 | m5-6Y57 | HD515 | DW1820A

Beitrag von „ntht1md“ vom 25. November 2020, 11:01

[Zitat von marcu5](#)

Update

Bluetooth	Wireless Internet access	Sleep	Audio	USB
OK	Partially	Broken	OK	Partially
Bluetooth works via USB and therefore requires USB Kext Airpod Pros and Magic Mouse were recognized without any problems, as in the 5GHz WLAN, also uninterrupted music. Even with a speed test	Works, but not all networks are found. A round of Geforce Now was stable possible. But it is not yet fully functional and the speed is far from optimal.	No solution in sight yet.	Works very well except for the headphone jack, there is no sound.	USB A works to the full. The two types C do not work and the MiniHDMI was not tested because I do not have such a plug.

Update 06/22

New wifi card has also come to China BCM94360NG. Runs perfectly OOB without device entries in the config.plist

Alles anzeigen

Dear Sir,

I have a Dell Latitude 7370 M5 6Y57. Can you share your EFI folder? I look forward to receiving your efi. Thank you so much.

Your sincerely