

# wlan BCM94331CD OpenCore0.6.4 BigSur Ryzentosh

Beitrag von „GenuineJakob“ vom 22. Dezember 2020, 21:57

**EDIT:** Anscheinend wird die Karte in BigSur nicht mehr unterstützt, schaut mal hier:  
<https://www.hackintosh-forum.de/forum/thread/51969>

Hi, habt ihr die Karte denn mal mit einem anderen Betriebssystem getestet?

Ich habe so ziemlich den gleichen Adapter und bei mir wurde die Karte von meinem Mainboard aus nicht erkannt, unabhängig des Betriebssystems. Ich hatte mich damals bei ASRock gemeldet und die haben mir innerhalb von 4 Tagen ein [BIOS Update](#) gebastelt.

Testet am besten mal ein anderes Betriebssystem, schaut im BIOS oder an einem anderen Rechner.

## Beta BIOS

Version	Date	Size	Update BIOS Under / How to Update	Description	Download
[Beta] 2.50B	2017/12/18	5.19MB	<a href="#">Instant Flash</a>	1. Enhance M.2 compatibility when using a PCIe to M.2 adapter. 2. Enhance graphic card compatibility.	<a href="#">Global</a> <a href="#">China</a>
[Beta] 1.21D	2014/6/10	5.50MB	<a href="#">Instant Flash</a>	Improve USB mouse compatibility under BIOS.	<a href="#">Global</a> <a href="#">China</a>
[Beta] 1.01B	2014/5/7	5.47MB	<a href="#">Instant Flash</a>	Improve SATA Express performance.	<a href="#">Global</a> <a href="#">China</a>
[Beta] 0.20G	2014/5/2	5.47MB	<a href="#">Instant Flash</a>	Improve OC & performance.	<a href="#">Global</a> <a href="#">China</a>