

# Problem nach BIOS-Flash

**Beitrag von „DeePoP“ vom 23. Dezember 2020, 00:23**

Alles klar!

Was mir gerade noch über den Weg gelaufen ist, ist das [hier](#):

*"Please note that it may be necessary to use a separate graphic card that has already got drivers installed earlier in the PC. This is because when the BIOS is corrupted and immediately after a reset, a start up screen will always appear with option for users to select the way to optimise the BIOS. This startup screen will not be shown by on-board graphic system as the BIOS has not yet been set up."*

Da ich ja auch nur mit der GTX ein Bild sehe, kling das für mich nachvollziehbar.