

# ASUS Rampage VI Extreme (original) with Radeon VII

Beitrag von „juantrix“ vom 6. Januar 2021, 09:39

Code

1. \* com.apple.driver.AppleEthernetAquantiaAqtion
2. \* Find: 0F84C002 0000
3. \* Replace: 660F1F44 0000

Some users appears with the same problem (disconnected).

Did you play with windows? (check it work with drivers installed, then shutdown, power Off completely). Try boot OSx.