

OpenCore | Catalina | Fujitsu Q920 (Haswell) | Installer stürzt ab

Beitrag von „grecedrummer“ vom 10. Januar 2021, 01:42

Intel BIOS settings

- Note: Most of these options may not be present in your firmware, we recommend matching up as closely as possible but don't be too concerned if many of these options are not available in your BIOS

#Disable

- Fast Boot
- Secure Boot
- Serial/COM Port
- Parallel Port
- VT-d (can be enabled if you set `DisableIoMapper` to YES)
- CSM
- Thunderbolt(For initial install, as Thunderbolt can cause issues if not setup correctly)
- Intel SGX
- Intel Platform Trust
- CFG Lock (MSR 0xE2 write protection)(**This must be off, if you can't find the option then enable `AppleXcpmCfgLock` under Kernel -> Quirks. Your hack will not boot with CFG-Lock enabled**)
 - For 10.10 and older, you'll need to enable `AppleCpuPmCfgLock` as well

#Enable

- VT-x
- Above 4G decoding
- Hyper-Threading
- Execute Disable Bit
- EHCI/XHCI Hand-off
- OS type: Windows 8.1/10 UEFI Mode
- [DVMT](#) Pre-Allocated(iGPU Memory): 64MB
- SATA Mode: AHCI

Deine Kexte waren alle veraltet. Probier mal diese EFI. Paar Veränderungen ...

SMBIOS Hardware

iMac14,4 Haswell with only iGPU