

# **Neuer Hackintosh nach 6 Jahren - passt das für ne VIDEO Workstation ?**

**Beitrag von „hannibal1969“ vom 16. Januar 2021, 03:02**

Well I don't know if it does make sense or help somebody but I have a workaround / solution. The Nitro does have a 4 Pin fan connection nearby the bios switch. If I connect a quiet Noctua fan to it it keeps spinning without noise and can be used to enforce continuously cooling to keep the temperatures down. Especially in the hot PWM area of the GPU. So it doesn't hysteresis anymore and keeps the card quite. Sure it will spin up under load but that's ok. The hysteresis was annoying.